



A × 10



M8×90 mm

B × 10




Ø8/Ø20 mm

C × 10



Ø8 mm

D × 10




M8×12 mm

E × 8




M6×20 mm

F × 2




60×30×3 mm

G × 4




Ø8/Ø45 mm

H × 1




12 mm

J × 1



4 mm

K × 1




Ø4×50 mm


L × 4




Ø25×3 mm




Box 1/1:




1900×1080×210mm




Ø30/57×130mm




1900×45×70mm




Ø30×190mm





95×820×500mm



95×820×500mm






1




+ ② + ③ + ④ + ⑤ x4 + ⑥


2





3





4

B × 10  Ø8/Ø20mm	C × 10  Ø8 mm	D × 10  M8×12 mm	H × 1  12 mm	
---	--	---	--	--






5

<p>E × 4</p>  <p>M6×20 mm</p>	<p>F × 2</p>  <p>60×30×3 mm</p>	<p>J × 1</p>  <p>4 mm</p>	
--	--	--	--






6

<p>E × 4</p>  <p>M6×20 mm</p>	<p>J × 1</p>  <p>4 mm</p>	
--	--	--



7

K x 1






8

G x 4



Ø8/Ø45 mm




9

L x 4




Ø25x3 mm






II







L



10



11



12

