




ASSEMBLY INSTRUCTIONS

LIST OF PARTS



Ax1



Bx1

LIST OF HARDWARE

| No. | Hardware | Q.ty |
|-----|----------|------|
| 1 | M8 x 25 | 04 |
| 2 | | 04 |
| 3 | | 04 |
| 4 | | 01 |

